

M/s. Switz International Pvt. Ltd., Unit-II, Village Bhimpore, Daman was issued 'consent to establish' to manufacture samosa patti-1000 MTPA (by way of RM-receiving & storage of raw material-quality checking-cleaning-prepare dough-shift dough into the hopper-automated sheeting in rondo line-sheets passes through the baking tunnel-manual stacking of sheets one top of the other-cutting of sheets as per size-pre cooling-packing) and spring roll patti-1000 MTPA (by way of RM- receiving & storage of raw material-quality checking-cleaning-preparation of batter--shift batter into the hopper-automated sheet formation in baking line-sheets bake over the baking drum-automated cutting of sheets as per size-stacking of sheets one top of the other-freezing-packing) (without any kind of washing and food processing process) under Water/Air Act and valid upto **31/05/2014**. The activity falls under **Green Category**.

A letter was issued to the unit on 08/01/2015 regarding re-inspect the unit. The unit has submitted a reply on 05/02/2015 and informing that their production is started and revisit the unit.


The unit was again re-inspected on 12/03/2015 and the observations are as under:


- The unit was in operation at the time of inspection.
- The unit has installed machinery such as spring roll patti line m/c, blast freezer, cold storage, mixing vessels, shifter m/c, baking drum m/c, automatic cutting m/c, packing m/c.
- The unit is manufacturing only spring roll patti and other product i.e. samosa patti is not manufactured at the time of inspection.
- The process includes mainly RM- receiving & storage of raw material-quality checking-cleaning-preparation of batter--shift batter into the hopper-automated sheet formation in baking line-sheets bake over the baking drum-automated cutting of sheets as per size-stacking of sheets one top of the other-freezing-packing.

- The unit is not doing any kind of food processing process at the time of inspection.
- The unit person has informed that washing of mixing vessels is not required because of only one product is manufactured and the floor washing is being discharged through soak pit.
- As per analysis report, domestic effluent report submitted by the unit all the parameter as within the permissible limits of PCC.
- At the time of inspection, the unit has installed DG Set of 100 KVA-1 No and provided acoustic enclosure.
- The unit has installed displayed sign board.

In view of the above, the unit ask for details of waste water generation during vessels washing and floor washing with quantity and mode of treatment facility. Hence, a letter is prepared and placed in the file.

Member Secretary


27.03.15


27/3/2015

Dilip