

0-2292

N/5

Name of the unit	<b>ERA Polyplast</b>	
Address	Sr. No. 7/1 (1), Shed No. 1, Ground Floor, Vapi Daman Road, Dabhel, Daman.	
Area	Dabhel	
Category	<b>Category - II</b>	
Applied for	Consent to Operate	
Consent granted for	Consent to Establish for "Plastic granules (from 1 <sup>st</sup> generation inhouse waste)-600 MTPA, All kind of plastic packaging materials-600 MTPA"	
Sr. No.	Documents required	Submitted
1.	Application in Form XIII under Water Act.	Yes (C/141)
2.	Application in Form I under Air Act.	Yes (C/135)
3.	Declaration letter showing capital investment.	Yes (C/113)
4.	Consent fees demand draft of Rs. 2000/- under Water Act and Air Act.	Yes (C/315)
5.	Display Sign Board.	Yes (C/125)
6.	Application for authorization to handle hazardous waste and industry data sheet in Form - I.	Yes (C/131)
7.	Industry Data Sheet Format	Yes (C/123)
8.	Copy of hazardous waste manifest in Form 13.	N.A.
9.	Copy of membership of common TSDF.	N.A.
10.	Copy of analysis of treated effluent.	N.A.
11.	Copy of stack monitoring report and ambient air quality monitoring report.	N.A.
Effluent discharge with quantity		
	Consumption	Discharge
Domestic water	200 Lit./Day	200 Lit./Day
Industrial water (Cooling)	500 Lit./Day	--
Air Emission		
Installation	Fuel used	Stack/Acoustic
N.A.	N.A.	N.A.
Details of Effluent Treatment Plant/APCDS		
ETP	N.A.	
APCDS	N.A.	
Monitoring Reports		
Effluent Norms		
	Norms as per consent	As per report
pH	6.5-9.0	--
Suspended Solids	Not to exceed 100 mg/Lit	--
BOD	Not to exceed 100 mg/Lit	--
COD	Not to exceed 250 mg/Lit	--
Oil & grease	Not to exceed 10 mg/Lit	--

**Observations and Recommendations :**

Previously, the unit was issued letter on 16/12/2015 as they have not installed any machineries and display signboard and to submit reply when all the machineries install. The unit has submitted reply on 12/07/2016 for re-inspect the unit. The unit was inspected on 24/08/2016 and at the time of inspection following observations were noted:

- The unit was in operation at the time of inspection.
- The unit has not installed Display signboard at the main gate.
- Raw material used in manufacturing process was Plastic scrape material only.
- Products being manufactured at the time of inspection were Plastic reprocessed granules only.
- Manufacturing process involved at the unit was Mixing– Extrusion – Pelletizing – and Packing.
- Machineries installed within the premises of the unit were Aglo/mixer m/c – 1 no, Extrusion (re-process granular) m/c – 1 no.
- Raw materials (Plastic scrape) were stored at separate area within the premises.
- The unit is not significant to pollution potential as there is no water used during any stage of process and no significant emission form the process.

In view of above, letter regarding to install Display signboard is prepared and placed in file.

*[Handwritten signature]*  
25/08/16

**Member Secretary**

*[Handwritten signature]*  
30/8/2016

SB