



Note: - The unit was issued Consent to Establish under Green Category vide No. PCC/DDD/G-3967/WA/AA/KG/04-05/1178 dated 30/12/2014. However, as per new notification No. PCC/DMN/13-(Part IV)/98-99/2014-15/1199 Dated 09/10/2015 the product falls under **Category-II.**

| | | |
|---|--|----------------|
| Name of the unit | M/s. Nine Metals | |
| Address | Sr. No. 380/1 (18-B), Modern Industrial Estate, Kachigam, Daman. | |
| Area | Kachigam | |
| Category | Category - II | |
| Applied for | Consent to Operate | |
| Consent granted for | Consent to Establish for 'Copper wire strips, tapes, bus bars, flats and tinned on copper wire – 750 MTPA, Bunched and stranded conductors and profiles paper covering on copper wire – 750 MTPA, Bright annealing of copper aluminium wire and strips and paper covering – 500 MTPA (By drawing only w/o any melting or pickling or phosphating process)' | |
| Sr. No. | Documents required | Submitted |
| 1. | Application in Form XIII under Water Act. | Yes (C/448) |
| 2. | Application in Form I under Air Act. | Yes (C/442) |
| 3. | Declaration letter showing capital investment. | Yes (C/434) |
| 4. | Consent fees of Rs. 15,540/- under Water Act and Air Act. | Yes (C/444) |
| 5. | Display Sign Board. | Yes (C/412) |
| 6. | Application for authorization to handle hazardous waste and industry data sheet in Form – I. | Yes (C/426) |
| 7. | Industry Data Sheet Format | Yes (C/420) |
| 8. | Copy of hazardous waste manifest in Form 13. | N.A. |
| 9. | Copy of membership of common TSDF. | Not submitted |
| 10. | Copy of analysis of treated effluent. | Not submitted |
| 11. | Copy of stack monitoring report and ambient air quality monitoring report. | N.A. |
| Effluent discharge with quantity | | |
| | Consumption | Discharge |
| Domestic water | 500 Lit./Day | 500 Lit./Day |
| Industrial water | -- | -- |
| Air Emission | | |
| Installation | Fuel used | Stack/Acoustic |
| N.A. | N.A. | N.A. |
| Details of Effluent Treatment Plant/APCDS | | |

| | | |
|--|--------------------------|---------------|
| ETP | Not installed | |
| APCDS | N.A. | |
| Monitoring Reports | | |
| Effluent Norms | | |
| | Norms as per consent | As per report |
| pH | 6.5-9.0 | -- |
| Suspended Solids | Not to exceed 100 mg/Lit | -- |
| BOD | Not to exceed 100 mg/Lit | -- |
| COD | Not to exceed 250 mg/Lit | -- |
| Oil & grease | Not to exceed 10 mg/Lit | -- |
| <p>Observations and Recommendations :</p> <p>The unit was inspected on 21/10/2016 and at the time of inspection following observations were noted:</p> <ul style="list-style-type: none"> ➤ Display signboard was prepared and placed at the main gate of premises. ➤ The unit was in operation at the time of inspection. ➤ Raw material used in manufacturing process was Copper rod (99.9 %) only. ➤ Products being manufactured at the time of inspection were Copper wire and Tinned Copper wire. ➤ Manufacturing process involved at the unit was Copper wire by drawing process and coating of tin on copper wire. ➤ Machineries installed within the premises of the unit were Copper drawing m/c – 8 nos, Bright annealing m/c – 1 no, Tin coating – 4 no. ➤ There is generation of wastewater from wire drawing process containing copper and directly dispose through drainage without any treatment. ➤ In addition, there is generation of waste oil, which is dispose through the same drainage. ➤ The generated copper waste/dust sold to scrape dealer, the unit did not submit details of the same. <p>In view of above, notice of direction is prepared and placed in file for approval, Sir.</p> | | |
|  | | |
| Member Secretary | | |


 27/10/2016